

APPENDIX

A.1 Organizational Chart (last updated FY2026)

A.2 Capital Request Form (last updated FY2026)

A.3 Conditional Assessment Form (last updated FY2026)

A.3.1 Rolling Stock

A.3.2 Facilities

A.4 Four-Year Capital Plan & Prioritization (last updated FY2026)

A.5 Asset Inventory and Condition Assessment (last updated FY2026)

A.5.1 Rolling Stock

A.5.2 Service Vehicles (Non-Revenue)

A.5.3 Equipment


A.6 Facilities Inventory and Condition Assessment (last updated FY2026)



A.6.1 Facilities Inventory

A.6.2 Facilities Condition Assessments


A.1 Organizational Chart (last updated FY2026)

The organizational charts below illustrate the company's hierarchical structure regarding the TAM plan. Paylocity provides the names of individuals currently occupying these positions.





PLANNING



A.2 Capital Request Form

The Capital Request Form is a Google Forms application used to submit capital proposals for the upcoming two fiscal years. Below is a screenshot of the form's interface.

Capital Request Form for 2027-2028

Please fill out separate forms for each request. Please have all requests in by July 15, 2026.

When you submit this form, the owner will see your name and email address.

* Required

1. Type of Request *

Select your answer

2. Department *

Select your answer

3. Location (check all that apply) *

- ☐ Dauphin County
- ☐ York County
- ☐ Adams County
- ☐ Columbia County
- ☐ Cumberland County
- ☐ Franklin County
- ☐ Montour County
- ☐ Northumberland County
- ☐ Perry County
- ☐ Union/Snyder Counties
- ☐ Harrisburg City

4. What service is the request for? *

☐ Fixed Route

☐ Paratransit

☐ Microtransit

☐ Admin

5. What is being requested? (Be as specific as possible: quantity, type, size) *

Enter your answer

6. Project Description *

Enter your answer

7. Estimated Cost *

Please enter a whole number

8. Priority Level *

Select your answer



☐ Send me an email receipt of my responses

Submit

A.3 Conditional Assessment Forms

A.3.1 Rolling Stock

TAM PLAN: Vehicle Condition Assessment Inspection Form

Inspector(s) Name:	
Inspection Date:	
Vehicle Number:	
Vehicle Identification Number (VIN):	
Vehicle Type:	
Vehicle Year:	
Vehicle Make & Model:	
Operating Division:	

Total Vehicle Condition Score:			0
Revenue and Non-Revenue Vehicle Condition Inspection Assessment			
ID	Main Component	Sub-Component	Condition Rating Score
A.	Engine		0
A.1.		Compression Test	
A.2.		Oil Usage/Levels	
A.3.		Noises	
A.4.		Coolant Level (leaks)	
A.5.		Radiator (leaks)	
A.6.		Air Filter	
A.7.		Engine Mounts/Brackets/Hardware (Condition)	
A.8.		Belts and Pulleys	
A.9.		Starter (Connections/Mounts)	
A.10.		Hoses, Tubes, Lines (leaks)	
A.11		Cat/Exhaust System (Pipes/Clamps)	
B.	Drivetrain		0

B.1.		Transmission Fluid (Levels/Use)	
B.2.		Rear End Fluid Levels/Use	
B.3.		Shift Quality (noises)	
B.4.		Reverse/Backup Alarm	
B.5.		Universal Joint/Driveshaft (tight)	
C.	Electrical		0
C.1.		Exterior Lighting	
C.2.		Interior Lighting	
C.3.		Dash Gauge (Function)	
C.4.		Wiring Condition	
C.5.		Destination Sign	
C.6.		Camera System	
C.7.		AVL Function	
C.8.		Battery Condition	
C.9.		Battery Voltage/Function	
C.10		Generator (Connections/Mounts)	
C.11.		Radio and Antenna (Function)	
C.12.		Starter (Connections/Mounts)	
D.	Suspension/ Steering		0
D.1.		Steering System (Play/Leaks/Wear)	
D.2.		Springs (Condition/Function)	
D.3.		Shocks (Condition/Function)	
D.4.		Struts (Condition/Function)	
D.5.		Suspension Bellow(S) (Function)	
D.6.		Suspension Leveling Valve(s) (Function)	
D.7.		Bushings/Mounts (Wear/Condition)	
D.8.		Tie Rod Ends (Wear/Condition)	

D.9.		Steering Box Fluid Level	
E.			0
E.1.		Tire Condition/Tread Depth	
E.2.		Lug Nuts (Tight)	
E.3.		Axle Nuts (Tight)	
E.4.		Brake/Shift Interlock (Function)	
E.5.		Emergency Brake (Function)	
E.6.		Brake Drums/Disks/Pads Lining (Condition/Wear)	
E.7.		Brake Fluid Levels/Use	
E.8.		Brake Hoses/Lines/Cables (Condition)	
E.9.		Brake Interlock (Air Leaks)	
E.10.		Front Hub Oil (If Applicable)	
E.11.		Brake Chamber (Function)	
E.12.		Air Brake Compressor (Function)	
E.13.		Air Brake Tank (Function)	
E.14.		Air Brake Lines (Leaks/Function)	
E.15.		Air Dryer (Leaks/Function)	
F.			0
F.1.		A/C Function	
F.2.		Heater Function	
G.			0
G.1.		Frame (Rust/Cracks/Condition)	
G.2.		King Pin (Condition/Wear)	
G.3.		Sub frame (Condition)	
H.			0
H.1.		Seats (Condition/Loose)	

H.2.		Grab Rail (Condition/Loose)	
H.3.		Panels/Trim (Loose/Condition)	
H.4.		Front Door (Operation)	
H.5.		Driver Seatbelt (Condition)	
H.6.		Driver Seat Mount (Condition)	
H.7.		Rubber Passenger Floor (Condition)	
H.8.		Passenger Seats (Condition)	
H.9.		Passenger Handrail (Loose/Condition)	
H.10.		Gear Shift Selector (Function)	
I.	Body: Exterior		0
I.1.		Window Glass	
I.2.		Body Panels (Condition/Broken/Rust)	
I.3.		Bumpers & Trim (Loose/Damaged)	
I.4.		Mirrors	
I.5.		Windshield Wipers (Function)	
I.6.		Body Damage	
I.7.		Passenger Bike Rack (Function/Condition)	
I.8.		Door Rubber Seal (Condition)	
I.9.		Window Rubber Seal (Condition)	
J.	ADA Amenities		0
J.1.		Wheelchair Lift/Ramp (Function/Condition)	
J.2.		Kneeler (Function)	
J.3.		Passenger Cord/Bell (Function)	
J.4.		Stop Announcement Speaker (Function)	
J.5.		Stop Announcement Display (Function)	

J.6.		Wheelchair Restraint System (Condition/Function)	
J.7.		AVL System (Function)	
J.8.		Passenger Counter (Function/Calibration)	
K.	General Safety		0
K.1.		Horn (Function)	
K.2.		Backup Alarm (Function)	
K.3.		Windshield Washer (Fluid Level & Function)	
K.4		Fire Suppression System	
K.5.		Roof Hatch/Emergency Exit	
K.6.		Emergency Exit Window Release Latch (Function)	
		Total Vehicle Condition Score:	0

NOTES:

Inspection Certification

By signing below, I confirm to the best of my ability, that the information presented in this document is true and based on factual information and assessment:

Inspector:

Name (print)
Date

Signature

A.3.2 Facilities

Conditions



TAM PLAN: Facility Condition Assessment Form

Inspector(s) Name:	test name
Inspection Date:	Saturday, January 0, 1900
Facility Name:	
Facility Address:	

Total Facility Condition Score	0	0.00
--------------------------------	---	------

Revenue and Non-Revenue Vehicle Condition Inspection Assessment				
ID	Main Component	Sub-Component	Condition Rating Score	Notes
A.	Substructure		0	
A.1.		Frame: Support Walls		
A.2.		Frame: Exterior Foundation		
A.3.		Concrete Slab		
A.4.		Frame: Beams, Trusses, & Columns		
B.	Roof		0	
B.1.		Drains, Gutters, & Downspouts		
B.2.		Support Structures		
B.3.		Surface: Shingles/Membrane		
B.4.		Mechanical		
C.	Exterior Shell		0	
C.1.		Exterior Windows		
C.2.		Exterior Doors		
C.3.		Structure: Siding Material		
C.4.		Garage Doors		

C.5.		Mechanical: Conduit, Gas Meters, Utility Box		
C.6.		Surface (Paint, Coating, Brick, etc.)		
D.	Interior: Offices, Break Room, Board Room, Mechanical		0	
D.1.		Floor Tile		
D.2.		Carpet		
D.3.		Doors		
D.4.		Structure: Walls, Foundation, Trusses		
D.5.		Surface: Paint		
D.6.		Insulation		
D.7.		Mechanical: Junction Box, Utility, Vents		
D.8.		Stairs: Surface/Structure		
D.9.		Ceiling Tiles		
E.	Interior: Maintenance Shop & Parts Storeroom		0	
E.1.		Structure: Walls, Frame, Trusses		
E.2.		Surface: Paint, Walls		
E.3.		Stairs: Surface/Structure		
E.4.		Flooring: Epoxy Coating, Uneven, Condition		
E.5.		Ventilation System		
E.6.		Plumbing: Leaks, Drains		
E.7.		Ceiling: Leaks; Cracks		
F.	Plumbing		0	
F.1.		Boiler/Furnace		
F.2.		Backflow Prevention Device		
F.3.		Water Heater		
F.4.		Exposed Pipes (Leaks) and Valves		
F.5.		Fixture: Water Closet		
F.6.		Fixture: Sink/Shower Faucet (leaks)		

F.7.		Fixture: Urinal		
G.			0	
G.1.		Chillers		
G.2.		Garage Ventilation Fan		
G.3.		Filters		
G.4.		Individual AC Units		
G.5.		Interior Venting/Diffuser, Vent Flu Pipes		
G.6.		Disconnects		
H.			0	
H.1.		Control Panel		
H.2.		Smoke Detection Devices		
H.3.		Heat Sensing Detectors		
H.4.		Strobe Alarm Lights		
H.5.		Audible Alarm		
H.6.		Phone Communication Module		
H.7.		Sprinkler System		
H.8.		Fire Alarm Pull Stations		
H.9.		Fire Extinguisher Cabinets		
H.10.		Power Supply Systems		
H.11.		Emergency Exit Signs		
H.12.		Stand Pipes/Plumbing		
H.13.		Emergency Interior Lights		
I.			0	
I.1.		Breaker Panel Box		
I.2.		Emergency Pull Box (Shut Off)		
I.3.		Junction Box		
I.4.		Light Switches		
I.5.		Electrical Outlets		

I.6.		Garage Door Controls		
I.7.		Connections		
I.8.		Light Fixtures (exterior)		
I.9.		Light Fixtures (interior)		
I.10.		Transformer		
J.	Equipment		0	
J.1.		Paint Booth		
J.2.		Bus Wash Rack System		
J.3.		Cyclone Vehicle Cleaning System		
J.4.		8 Station Lube System		
J.5.		Rotary Lift		
J.6.		Air Compressor		
J.7.		HQ GFI Bus Fare Collection Safe		
J.8.		Backup Generator		
J.9.		HQ Security CCTV System		
J.10.		Radio System (antenna, base, portables)		
K.	Site Grounds		0	
K.1.		Fencing & Gates (condition)		
K.2.		Roadways (condition)		
K.3.		Signage (condition)		
K.4.		Pavement Markings (parking lines)		
K.5.		Structural/Surface (pavement condition)		
K.6.		Sidewalk		
K.7.		Access Control Devices (function/condition)		
K.8.		Landscaping		
K.9.		Mechanical (Utilities, Light Posts)		

K.10.		Exterior Lighting		
-------	--	-------------------	--	--

NOTES:

Inspection Certification

By signing below, I confirm to the best of my ability, that the information presented in this document is true and based on factual information and assessment:

Inspector:

	<i>test name</i>	Saturday, January 0, 1900
Name (print)	Signature	Date

A.4 Four-Year Capital Plan & Prioritization (last updated FY2022)

			2027	2028	2029	2030		
Project Title	Sponser	Location	Total	Total	Total	Total	Project Total	
Shop Equipment	SRTA	Harrisburg	125,000	125,000	125,000	125,000	\$ 500,000.00	This project provides funds for the purchase of shop tools and equipment needed in the maintenance department.
Transit Vehicle Purchase	SRTA	Harrisburg	705,750	705,750	705,750	705,750	\$ 2,823,000.00	This project provides funds to replace fixed route vehicles that have met their useful life in miles and years.
Transit Vehicle Purchase	SRTA	Harrisburg	716,250	716,250	716,250	0	\$ 2,148,750.00	This project provides funds to replace fixed route vehicles that have met their useful life in miles and years.
Transit Vehicle Purchase	SRTA	Harrisburg	6,318,750	3,159,375	3,159,375	3,159,375	\$ 15,796,875.00	This project provides funds to replace fixed route vehicles that have met their useful life in miles and years.
Shared Ride Vehicle	SRTA	Harrisburg	550,000	0	0	0	\$ 550,000.00	This project provides funds to replace shared ride vehicles that have met their useful life in miles and years.
SRTA Operation/Maint (Facility)	SRTA	Harrisburg	9,000,000	0	0	0	\$ 9,000,000.00	This project provides funds for the planning, design, and construction of a new administrative and maintenance facility to support transit operations.
SRTA Operation/Maint (Facility)	SRTA	Harrisburg	0	0	0	0	\$ -	This project provides funds for the planning, design, and construction of a new administrative and maintenance facility to support transit operations.
Bus Stop/Shelters	SRTA	Harrisburg	1,350,000	0	0	0	\$ 1,350,000.00	This project provides funds for improvements and expansion of bus stops and passenger shelters to enhance safety and accessibility.
Fixed Route Bus Equipment	SRTA	Harrisburg	1,462,500	0	0	0	\$ 1,462,500.00	This project provides funds for the purchase and replacement of equipment necessary for fixed route bus operations.
Fixed Route Vehicles	SRTA	York	942,500	471,250	471,250	471,250	\$ 2,356,250.00	This project provides funds to replace fixed route vehicles that have met their useful life in miles and years.
Fixed Route Vehicles	SRTA	York	3,512,000	2,125,000			\$ 5,637,000.00	This project provides funds to replace fixed route vehicles that have met their useful life in miles and years.
Fixed Route Vehicles	SRTA	York	366,000	2,042,000	1,021,000	1,021,000	\$ 4,450,000.00	This project provides funds to replace fixed route vehicles that have met their useful life in miles and years.
Bus Stop/Shelter Improvement/Expansion	SRTA	York	1,350,000	0	0	0	\$ 1,350,000.00	This project provides funds for improvements and expansion of bus stops and passenger shelters to enhance safety and accessibility.
Hanover - Transit Vehicles	SRTA	York	1,539,835	250,000	256,161	263,845	\$ 2,309,840.63	This project provides funds to replace transit vehicles serving the Hanover service area that have met their useful life.
Fixed Route Bus Equipment	SRTA	York	812,500	812,500			\$ 1,625,000.00	This project provides funds for the purchase and replacement of equipment necessary for fixed route bus operations.
Shop Equipment	SRTA	York	75,000	75,000	75,000	75,000	\$ 300,000.00	This project provides funds for the purchase of shop tools and equipment needed in the maintenance department.
Microtransit Vehicles	SRTA	Chambersburg	500,000	500,000	0	600,000	\$ 1,600,000.00	This project provides funds to replace microtransit vehicles that have met their useful life in miles and years
Microtransit Vehicles	SRTA	Bloomsburg	650,000	650,000	0	0	\$ 1,300,000	This project provides funds to replace/expand microtransit vehicles that have met their useful life in miles and years.

A.5 Asset Inventory and Condition Assessment (last updated FY2022)

A.5.1 Rolling Stock

Asset ID	Organization	VIN	Manufacturer	Model	Year	In Service Date	Type	Subtype	Cost (Purchase)	Primary Mode	Service Status	Odometer Reading	TERM Condition	Scheduled Replacement Year	Last Life Cycle Action	Life Cycle Action Date
413	SRTA	15GGD211771078326	GIL - Gillig Corporation	LOW FLOOR BRT	2007	6/1/2010	Over-the-road Bus	Bus Commuter/Suburban	160000	Commuter Bus	Out of Service	566489	1	26-27	Mileage	7/9/2026
1106	SRTA	15GGD3011B1178938	GIL - Gillig Corporation	Hybrid	2011	4/21/2011	Bus	Bus Std 40 FT	543642	Bus	In Service	378518	3	28-29	Mileage	7/9/2026
1109	SRTA	15GGD3011B1178941	GIL - Gillig Corporation	Hybrid	2011	4/21/2011	Bus	Bus Std 40 FT	543642	Bus	Out of Service	328650	3	27-28	Mileage	7/9/2026
1202	SRTA	15GGB2719C1179018	GIL - Gillig Corporation	Low Floor	2012	1/16/2012	Bus	Bus Std 35 FT	345513	Bus	In Service	363503	3	28-29	Mileage	7/9/2026
1203	SRTA	15GGB2710C1179019	GIL - Gillig Corporation	Low Floor	2012	1/16/2012	Bus	Bus Std 35 FT	345513	Bus	In Service	351788	3	28-29	Mileage	7/9/2026
1204	SRTA	15GGB2717C1179020	GIL - Gillig Corporation	Low Floor	2012	1/17/2012	Bus	Bus Std 35 FT	345513	Bus	In Service	393630	3	28-29	Mileage	7/9/2026
1205	SRTA	15GGB2719C1179021	GIL - Gillig Corporation	Low Floor	2012	1/17/2012	Bus	Bus Std 35 FT	345513	Bus	In Service	363277	3	28-29	Mileage	7/9/2026
1206	SRTA	15GGB2710C1179022	GIL - Gillig Corporation	Low Floor	2012	1/20/2012	Bus	Bus Std 35 FT	345513	Bus	In Service	370593	3	28-29	Mileage	7/9/2026
1207	SRTA	15GGB2712C1179023	GIL - Gillig Corporation	Low Floor	2012	1/19/2012	Bus	Bus Std 35 FT	345513	Bus	In Service	401919	3	28-29	Mileage	7/9/2026
1301	SRTA	15GGD2712D1181737	GIL - Gillig Corporation	Low Floor	2013	6/14/2013	Bus	Bus Std 40 FT	393813	Bus	In Service	366061	3	28-29	Mileage	7/9/2026
1302	SRTA	15GGD2714D1181738	GIL - Gillig Corporation	Low Floor	2013	6/17/2013	Bus	Bus Std 40 FT	393813	Bus	In Service	357864	3	28-29	Mileage	7/10/2026
1303	SRTA	15GGD2716D1181739	GIL - Gillig Corporation	Low Floor	2013	6/18/2013	Bus	Bus Std 40 FT	393813	Bus	In Service	349259	3	28-29	Mileage	7/9/2026
1304	SRTA	15GGD2712D1181740	GIL - Gillig Corporation	Low Floor	2013	6/19/2013	Bus	Bus Std 40 FT	393813	Bus	In Service	344803	3	28-29	Mileage	7/9/2026
1305	SRTA	15GGD2714D1181741	GIL - Gillig Corporation	Low Floor	2013	6/20/2013	Bus	Bus Std 40 FT	393813	Bus	In Service	337823	3	28-29	Mileage	7/9/2026
1306	SRTA	15GGD2716D1181742	GIL - Gillig Corporation	Low Floor	2013	6/20/2013	Bus	Bus Std 40 FT	393813	Bus	In Service	346223	3	28-29	Mileage	7/9/2026
1307	SRTA	15GGD2718D1181743	GIL - Gillig Corporation	Low Floor	2013	6/21/2013	Bus	Bus Std 40 FT	393813	Bus	In Service	362223	3	28-29	Mileage	7/9/2026
1401	SRTA	15GGD2716E1183069	GIL - Gillig Corporation	Low Floor	2014	4/1/2014	Bus	Bus Std 40 FT	394370	Bus	In Service	335358	3	28-29	Mileage	7/9/2026
1402	SRTA	15GGD2712E1183070	GIL - Gillig Corporation	Low Floor	2014	5/6/2014	Bus	Bus Std 40 FT	394370	Bus	In Service	342731	3	28-29	Mileage	7/9/2026
1403	SRTA	15GGD2714E1183071	GIL - Gillig Corporation	Low Floor	2014	5/27/2014	Bus	Bus Std 40 FT	394370	Bus	In Service	350205	3	28-29	Mileage	7/9/2026
1404	SRTA	15GGD2716E1183072	GIL - Gillig Corporation	Low Floor	2014	3/24/2014	Bus	Bus Std 40 FT	394370	Bus	In Service	327915	3	28-29	Mileage	7/9/2026
1405	SRTA	15GGE2717E1092549	GIL - Gillig Corporation	Low Floor	2014	5/9/2014	Bus	Bus 30 FT	376780	Bus	In Service	200318	3	28-29	Mileage	7/9/2026
1406	SRTA	15GGE2713E1092550	GIL - Gillig Corporation	Low Floor	2014	4/25/2014	Bus	Bus 30 FT	376780	Bus	In Service	168046	3	28-29	Mileage	7/9/2026
1601	SRTA	15GGD2714G1186233	GIL - Gillig Corporation	Low Floor	2016	9/12/2016	Bus	Bus Std 40 FT	416950	Bus	In Service	287000	3	28-29	Mileage	7/9/2026
1602	SRTA	15GGD2716G1186234	GIL - Gillig Corporation	Low Floor	2016	9/12/2016	Bus	Bus Std 40 FT	416950	Bus	In Service	261320	3	28-29	Mileage	7/9/2026
1603	SRTA	15GGD2718G1186235	GIL - Gillig Corporation	Low Floor	2016	9/12/2016	Bus	Bus Std 40 FT	416950	Bus	In Service	269779	3	28-29	Mileage	7/9/2026
1604	SRTA	15GGD272XG1186236	GIL - Gillig Corporation	Low Floor	2016	10/18/2016	Bus	Bus Std 40 FT	416950	Bus	In Service	277518	4	28-29	Mileage	7/9/2026
1701	SRTA	15GGB2713H3189913	GIL - Gillig Corporation	35' Low Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	249288	4	29-30	Mileage	7/9/2026
1702	SRTA	15GGB2715H3189914	GIL - Gillig Corporation	35' Low Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	245505	4	29-30	Mileage	7/9/2026

1703	SRTA	15GGB2717H3189915	GIL - Gillig Corporation	35' Low floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	219576	4	29-30	Mileage	7/9/2026
1704	SRTA	15GGB2719H3189916	GIL - Gillig Corporation	35' Low Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	267576	4	29-30	Mileage	7/9/2026
1705	SRTA	15GGB2710H3189917	GIL - Gillig Corporation	35' Low Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	250823	4	29-30	Mileage	7/9/2026
1706	SRTA	15GGB2712H3189918	GIL - Gillig Corporation	35' ow Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	235443	4	29-30	Mileage	7/9/2026
1707	SRTA	15GGB2714H3189919	GIL - Gillig Corporation	35' Low Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	260449	4	29-30	Mileage	7/9/2026
1708	SRTA	15GGB2710H3189920	GIL - Gillig Corporation	35' Low Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	262049	4	29-30	Mileage	7/9/2026
1709	SRTA	15GGB2712H3189921	GIL - Gillig Corporation	35' Low Floor	2017	12/1/2017	Bus	Bus Std 35 FT	414751	Bus	In Service	248949	4	29-30	Mileage	7/9/2026
1822	SRTA	5FYD2UM111U023206	NFA - New Flyer of America	D-60LF	2003	2/25/2021	Articulated Bus	Bus Articulated	325000	Bus	In Service	49049	3	28-29	Mileage	7/9/2026
1823	SRTA	5FYD2UM181U023204	NFA - New Flyer of America	D-60LF	2003	2/25/2021	Articulated Bus	Bus Articulated	325000	Bus	Out of Service	14884	1	28-29	Mileage	7/9/2026
1901	SRTA	15GGD2714K3192921	GIL - Gillig Corporation		2019	4/3/2020	Bus	Bus Std 40 FT	473729	Bus	In Service	201320	4	31-32	Mileage	7/9/2026
1902	SRTA	15GGD2716K3192922	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	473729	Bus	In Service	246012	4	31-32	Mileage	7/9/2026
1903	SRTA	15GGD2718K3192923	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	473729	Bus	In Service	261808	4	31-32	Mileage	7/9/2026
1904	SRTA	15GGD271XK3192924	GIL - Gillig Corporation	Low Floor	2019	4/2/2020	Bus	Bus Std 40 FT	473729	Bus	In Service	239932	4	31-32	Mileage	7/9/2026
1905	SRTA	15GGD2711K3192925	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	473729	Bus	In Service	231079	4	31-32	Mileage	7/9/2026
1906	SRTA	15GGD2713K3192912	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	476575	Bus	In Service	204157	4	31-32	Mileage	7/9/2026
1907	SRTA	15GGD2715K3192913	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	476575	Bus	In Service	208175	4	31-32	Mileage	7/9/2026
1908	SRTA	15GGD2717K3192914	GIL - Gillig Corporation	Low Floor	2019	9/30/2019	Bus	Bus Std 40 FT	476575	Bus	In Service	173707	4	31-32	Mileage	7/9/2026
1909	SRTA	15GGD2719K3192915	GIL - Gillig Corporation	Low Floor	2019	9/30/2019	Bus	Bus Std 40 FT	476575	Bus	In Service	209404	4	31-32	Mileage	7/9/2026
1910	SRTA	15GGD2710K3192916	GIL - Gillig Corporation	Low Floor	2019	9/30/2019	Bus	Bus Std 40 FT	476575	Bus	In Service	210602	4	31-32	Mileage	7/9/2026
1911	SRTA	15GGD2712K3192917	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	476575	Bus	In Service	210259	4	31-32	Mileage	7/9/2026
1912	SRTA	15GGD2714K3192918	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	476575	Bus	In Service	214129	4	31-32	Mileage	7/9/2026
1913	SRTA	15GGD2716K3192919	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	476575	Bus	In Service	210520	4	31-32	Mileage	7/9/2026
1914	SRTA	15GGD2712K3192920	GIL - Gillig Corporation	Low Floor	2019	4/3/2020	Bus	Bus Std 40 FT	476575	Bus	In Service	207782	4	31-32	Mileage	7/9/2026
2101	SRTA	15GGD2712M3195481	GIL - Gillig Corporation	40' Low Floor Suburban	2021	7/1/2021	Bus	Bus Commuter/Suburban	499929	Bus	In Service	182568	4	33-34	Mileage	7/9/2026
2102	SRTA	15GGD2714M3195482	GIL - Gillig Corporation	40' Low Floor Suburban	2021	7/1/2021	Bus	Bus Commuter/Suburban	499929	Bus	In Service	195654	4	33-34	Mileage	7/9/2026
2103	SRTA	15GGD2716M3195483	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	154740	4	33-34	Mileage	7/9/2026
2104	SRTA	15GGD2718M3195484	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	162117	4	33-34	Mileage	7/9/2026
2105	SRTA	15GGD271XM3195485	GIL - Gillig Corporation	Low Floor	2021	3/29/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	159700	4	32-33	Mileage	7/9/2026
2106	SRTA	15GGD2711M3195486	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	154917	4	33-34	Mileage	7/9/2026
2107	SRTA	15GGD2713M3195487	GIL - Gillig Corporation	Low Floor	2021	4/21/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	155850	4	32-33	Mileage	7/9/2026

2108	SRTA	15GGD2715M3195488	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	164791	4	33-34	Mileage	7/9/2026
2109	SRTA	15GGD2717M3195489	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	166404	4	33-34	Mileage	7/9/2026
2110	SRTA	15GGD2713M3195490	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	155429	4	33-34	Mileage	7/9/2026
2111	SRTA	15GGD2715M3195491	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	131447	4	33-34	Mileage	7/9/2026
2112	SRTA	15GGD2717M3195492	GIL - Gillig Corporation	40' Low Floor	2021	7/1/2021	Bus	Bus Std 40 FT	501365	Bus	In Service	145954	4	33-34	Mileage	7/9/2026
2113	SRTA	15GGE2716M3093887	GIL - Gillig Corporation	29'	2021	7/1/2021	Bus	Bus 30 FT	480696	Bus	In Service	72520	4	31-32	Mileage	7/9/2026
2114	SRTA	15GGE2718M3093888	GIL - Gillig Corporation	29'	2021	7/1/2021	Bus	Bus 30 FT	480696	Bus	In Service	54540	4	31-32	Mileage	7/9/2026
2115	SRTA	15GGE271XM3093889	GIL - Gillig Corporation	29'	2021	7/1/2021	Bus	Bus < 30 FT	480696	Bus	In Service	77001	4	28-29	Mileage	7/9/2026
218	SRTA	15GGE3115H3093111	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus 30 FT	469573	Bus	In Service	374828	4	27-28	Mileage	7/9/2026
219	SRTA	15GGE3117H3093112	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus 30 FT	469573	Bus	In Service	400230	4	27-28	Mileage	7/9/2026
220	SRTA	15GGE3119H3093113	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus 30 FT	469573	Bus	In Service	397418	4	27-28	Mileage	7/9/2026
221	SRTA	15GGE3110H3093114	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus 30 FT	472494	Bus	In Service	245644	4	28-29	Mileage	7/9/2026
222	SRTA	15GGE3112H3093115	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus 30 FT	472494	Bus	In Service	405989	4	27-28	Mileage	7/10/2026
223	SRTA	15GGE3114H3093116	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus 30 FT	472494	Bus	In Service	371683	4	27-28	Mileage	7/9/2026
224	SRTA	15GGE3116H3093117	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus 30 FT	472494	Bus	In Service	428632	4	27-28	Mileage	7/9/2026
225	SRTA	15GGE3115J3093535	GIL - Gillig Corporation	LOWFLOOR	2018	1/9/2019	Bus	Bus 30 FT	515069	Bus	In Service	347235	4	28-29	Mileage	7/9/2026
226	SRTA	15GGE3117J3093536	GIL - Gillig Corporation	LOWFLOOR	2018	1/9/2019	Bus	Bus 30 FT	516854	Bus	In Service	229970	4	28-29	Mileage	7/9/2026
227	SRTA	15GGE3114L3093612	GIL - Gillig Corporation	LOW FLOOR	2020	1/9/2020	Bus	Bus 30 FT	498597	Bus	In Service	302507	4	29-30	Mileage	7/9/2026
228	SRTA	15GGE3116L3093613	GIL - Gillig Corporation	LOW FLOOR	2020	1/9/2020	Bus	Bus 30 FT	498597	Bus	In Service	297460	4	29-30	Mileage	7/9/2026
316	SRTA	15GGD3018D1181726	GIL - Gillig Corporation	LOW FLOOR BRT	2013	2/1/2013	Bus	Bus Std 40 FT	602054	Bus	In Service	492597	1	27-28	Mileage	7/9/2026
317	SRTA	15GGD301XD1181727	GIL - Gillig Corporation	LOW FLOOR BRT	2013	2/1/2013	Bus	Bus Std 40 FT	602054	Bus	In Service	526019	1	27-28	Mileage	7/9/2026
318	SRTA	15GGD3011D1181728	GIL - Gillig Corporation	LOW FLOOR BRT	2013	2/1/2013	Bus	Bus Std 40 FT	602054	Bus	In Service	561354	1	26-27	Mileage	7/9/2026
327	SRTA	15GGB3116H3186874	GIL - Gillig Corporation	Standard Low Floor	2017	8/1/2017	Bus	Bus Std 35 FT	487662	Bus	In Service	344357	4	29-30	Mileage	7/9/2026
328	SRTA	15GGB3118K3194413	GIL - Gillig Corporation	LOW FLOOR	2020	1/7/2020	Bus	Bus Std 35 FT	534909	Bus	In Service	248564	4	31-32	Mileage	7/9/2026
329	SRTA	15GGD311XK3194414	GIL - Gillig Corporation	LOW FLOOR	2020	1/14/2020	Bus	Bus Std 35 FT	534909	Bus	In Service	240575	4	31-32	Mileage	7/9/2026
330	SRTA	15GGB3114K3194415	GIL - Gillig Corporation	LOW FLOOR	2020	1/27/2020	Bus	Bus Std 35 FT	534909	Bus	In Service	217237	4	31-32	Mileage	7/9/2026
331	SRTA	15GGD3113K3194416	GIL - Gillig Corporation	LOW FLOOR	2020	1/27/2020	Bus	Bus Std 35 FT	534909	Bus	In Service	200579	4	31-32	Mileage	7/9/2026
332	SRTA	15GGD3113K3193765	GIL - Gillig Corporation	LOW FLOOR	2020	1/27/2020	Bus	Bus Std 35 FT	526420	Bus	In Service	224534	4	31-32	Mileage	7/9/2026
333	SRTA	15GGB3116K3193766	GIL - Gillig Corporation	LOW FLOOR	2020	5/4/2020	Bus	Bus Std 35 FT	526420	Bus	In Service	201133	4	31-32	Mileage	7/9/2026
334	SRTA	15GGB3118K3193767	GIL - Gillig Corporation	LOW FLOOR	2020	1/27/2020	Bus	Bus Std 35 FT	526420	Bus	In Service	241683	4	31-32	Mileage	7/9/2026
335	SRTA	15GGB311XK3193768	GIL - Gillig Corporation	LOW FLOOR	2020	1/27/2020	Bus	Bus Std 35 FT	526420	Bus	In Service	206161	4	31-32	Mileage	7/9/2026
336	SRTA	15GGD3117L3193769	GIL - Gillig Corporation	LOW FLOOR	2020	1/14/2020	Bus	Bus Std 40 FT	503632	Bus	In Service	210662	4	31-32	Mileage	7/9/2026

337	SRTA	15GGD3113L3193770	GIL - Gillig Corporation	LOW FLOOR	2020	1/14/2020	Bus	Bus Std 40 FT	503632	Bus	In Service	250957	4	31-32	Mileage	7/9/2026
415	SRTA	1M8PDMBA5BP059654	MCI - Motor Coach Industries International (DINA)	D4500 Coach	2011	2/1/2013	Over-the-road Bus	Bus Commuter/Suburban	450000	Commuter Bus	Out of Service	351866	1	28-29	Mileage	7/9/2026
416	SRTA	1M8PDMAA1BP059653	MCI - Motor Coach Industries International (DINA)	D4500 Coach	2011	5/1/2013	Over-the-road Bus	Bus Commuter/Suburban	450000	Commuter Bus	Out of Service	337181	1	28-29	Mileage	7/9/2026
417	SRTA	15GGD2713D1183299	GIL - Gillig Corporation	Low Floor BRT	2013	10/1/2013	Over-the-road Bus	Bus Commuter/Suburban	453449	Commuter Bus	In Service	405434	4	28-29	Mileage	7/9/2026
418	SRTA	15GGD2714E1183300	GIL - Gillig Corporation	Low Floor BRT	2014	4/1/2015	Over-the-road Bus	Bus Commuter/Suburban	485376	Commuter Bus	In Service	472045	4	28-29	Mileage	7/9/2026
419	SRTA	15GGD211171078337	GIL - Gillig Corporation	Low Floor BRT	2007	10/24/2014	Over-the-road Bus	Bus Commuter/Suburban	25467	Commuter Bus	In Service	509839	3	27-28	Mileage	7/9/2026
421	SRTA	1M8SDMLA6CP012742	MCI - Motor Coach Industries International (DINA)	D4000	2012	7/27/2015	Over-the-road Bus	Bus Commuter/Suburban	528650	Commuter Bus	In Service	241285	3	28-29	Mileage	7/9/2026
422	SRTA	1M8PDM3A4HP014731	MCI - Motor Coach Industries International (DINA)	D4500	2017	11/1/2017	Over-the-road Bus	Bus Commuter/Suburban	678347	Commuter Bus	In Service	246231	4	29-30	Mileage	7/9/2026
423	SRTA	1M8PDM3A6HP014732	MCI - Motor Coach Industries International (DINA)	D4500	2017	11/1/2017	Over-the-road Bus	Bus Commuter/Suburban	678347	Commuter Bus	In Service	244024	4	29-30	Mileage	7/9/2026
601	SRTA	15GGD211571078325	GIL - Gillig Corporation	Low Floor BRT	2007	1/1/2015	Over-the-road Bus	Bus Commuter/Suburban	160000	Commuter Bus	In Service	645259	3	26-27	Mileage	7/9/2026

A.5.2 Service Vehicles (Non-Revenue)

Asset ID	Odometer Reading	Type	Subtype	VIN	In Service Date	TERM Rating	TERM Condition	Scheduled Replacement Cost	Organization	Year	Direct Capital Responsibility	Manufacturer	Model	Replacement Status	Primary Mode	Capital Responsibility %	Cost (Purchase)	Scheduled Replacement Year	Policy Replacement Year	Disposition Date	Service Status	Last Life Cycle Action	Life Cycle Action Date
2210	29069	Trucks and other Rubber Tire Vehicles	Pickup Truck	1FTBF2BN0NEG15413	5/30/2023	Poor	1	31,995	SRTA	2022	Yes	FRD - Ford Motor Corporation	F-250	By Policy	Bus	1	30625	26-27	26-27		In Service	Mileage	7/10/2026
2211	7155	Trucks and other Rubber Tire Vehicles	Pickup Truck	1FTBF2BN9NEG15412	5/28/2023	Poor	1	31,995	SRTA	2022	Yes	FRD - Ford Motor Corporation	F-250	By Policy	Bus	1	30625	26-27	26-27		In Service	Mileage	7/10/2026
2268	13061	Automobiles	Sports Utility Vehicle	2FMPK4G98PBA23602	4/4/2023	Poor	1	37,024	SRTA	2023	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Other Vehicles Operated	1	35439	26-27	26-27		In Service	Mileage	7/10/2026
2203	27679	Automobiles	Sports Utility Vehicle	2FMPK4G95NBA55081	5/27/2022	Poor	1	33,208	SRTA	2022	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Other Vehicles Operated	1	31440	26-27	25-26		In Service	Mileage	7/10/2026
2202	22017	Automobiles	Sports Utility Vehicle	2FMPK4G94NBA54746	5/27/2022	Poor	1	33,208	SRTA	2022	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Other Vehicles Operated	1	31440	26-27	25-26		In Service	Mileage	7/10/2026
2201	36205	Automobiles	Sports Utility Vehicle	2FMPK4G90NBA54341	5/27/2022	Poor	1	33,208	SRTA	2022	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Other Vehicles Operated	1	31440	26-27	25-26		In Service	Mileage	7/10/2026
2200	30777	Automobiles	Sports Utility Vehicle	2FMPK4G96NBA53274	5/27/2022	Poor	1	33,208	SRTA	2022	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Other Vehicles Operated	1	31440	26-27	25-26		In Service	Mileage	7/10/2026
836	41295	Automobiles	Sports Utility Vehicle	2FMPK4G9X MBA54667	11/23/2021	Poor	1	30,947	SRTA	2021	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Other Vehicles Operated	1	29300	26-27	25-26		In Service	Mileage	7/10/2026
832	45595	Automobiles	Van	3C6TRVNG9LE137401	9/10/2020	Poor	1	30,819	SRTA	2020	Yes	DTD - Dodge Division - Chrysler Corporation	Promaster	Underway	Bus	1	29499	26-27	24-25		In Service	Mileage	7/10/2026
834	51759	Automobiles	Sports Utility Vehicle	2FMPK4G98LBA05594	8/27/2020	Poor	1	31,606	SRTA	2020	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Bus	1	29598	26-27	24-25		In Service	Mileage	7/10/2026
833	24619	Automobiles	Sports Utility Vehicle	2FMPK4G93LBA38969	8/27/2020	Poor	1	31,606	SRTA	2020	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Bus	1	29598	26-27	24-25		In Service	Mileage	7/10/2026
835	59921	Automobiles	Sports Utility Vehicle	2FMPK4J96LBA40112	8/27/2020	Poor	1	35,872	SRTA	2020	Yes	FRD - Ford Motor Corporation	Edge	By Policy	Bus	1	33593	26-27	24-25		In Service	Mileage	7/10/2026
122	19673	Trucks and other Rubber Tire Vehicles	Pickup Truck	1FTBF2B68KEG08732	2/28/2020	Poor	1	33,709	SRTA	2019	Yes	FRD - Ford Motor Corporation	F-250	By Policy	Bus	1	31224	26-27	23-24		In Service	Mileage	7/10/2026
831	440	Trucks and other Rubber Tire Vehicles	Other Support Vehicle	00000000000070533	9/10/2018	Poor	1	23,466	SRTA	2010	Yes	Kubota	L4310	By Policy	Bus	1	21500	26-27	20-21		In Service	Mileage	7/10/2026
829	16323	Automobiles	Sedan/Station Wagon	1G1BC5SM0J7205896	7/23/2018	Poor	1	18,566	SRTA	2018	Yes	CMD - Chevrolet Motor Division - GMC	Cruz	By Policy	Bus	1	16642	28-29	28-29		In Service	Mileage	7/10/2026
830	47524	Automobiles	Sedan/Station Wagon	1G1BC5SM8J7205175	7/23/2018	Poor	1	18,518	SRTA	2018	Yes	CMD - Chevrolet Motor Division - GMC	Cruz	By Policy	Bus	1	16599	28-29	28-29		In Service	Mileage	7/10/2026
826	36772	Automobiles	Sports Utility Vehicle	2GNAXREV9J6315386	5/21/2018	Poor	1	25,408	SRTA	2018	Yes	CMD - Chevrolet Motor Division - GMC	Equinox	By Policy	Bus	1	23026	26-27	21-22		In Service	Mileage	7/10/2026
827	90346	Automobiles	Sports Utility Vehicle	2GNAXREV4J6313089	5/21/2018	Poor	1	24,859	SRTA	2018	Yes	CMD - Chevrolet Motor Division - GMC	Equinox	Underway	Bus	1	23026	26-27	21-22		In Service	Mileage	7/10/2026
828	102669	Automobiles	Sports Utility Vehicle	2GNAXREV6J6312946	5/21/2018	Poor	1	24,859	SRTA	2018	Yes	CMD - Chevrolet Motor Division - GMC	Equinox	Underway	Bus	1	23026	26-27	21-22		In Service	Mileage	7/10/2026
EUV3	0	Automobiles	Other Support Vehicle	00000000005306740	9/14/2016	Poor	1	4,871	SRTA	2013	Yes	ZZZ - Other (Describe)	EZGO RXV Electric	By Policy	Bus	1	4366	26-27	18-19		Out of Service	Mileage	7/10/2026

EUV 2	0	Automobiles	Other Support Vehicle	000000000 05300744	9/14/2016	Poor	1	4,871	SRTA	2013	Yes	ZZZ - Other (Describe)	EZGO RXV Electric	By Policy	Bus	1	4366	26-27	18-19	Out of Service	Mileage	7/10/2026
EUV 1	0	Automobiles	Other Support Vehicle	000000000 05306791	9/14/2016	Poor	1	4,871	SRTA	2013	Yes	ZZZ - Other (Describe)	EZGO RXV Electric	By Policy	Bus	1	4366	26-27	18-19	In Service	Mileage	7/10/2026
825	78766	Automobiles	Sedan/Station Wagon	1FADP3F27GL373221	8/1/2016	Poor	1	20,852	SRTA	2016	Yes	FRD - Ford Motor Corporation	Focus	By Policy	Bus	1	18691	26-27	26-27	In Service	Mileage	7/10/2026
824	88555	Automobiles	Sedan/Station Wagon	1FADP3F25GL373220	8/1/2016	Poor	1	20,852	SRTA	2016	Yes	FRD - Ford Motor Corporation	Focus	By Policy	Bus	1	18691	26-27	26-27	In Service	Mileage	7/10/2026
823	29313	Trucks and other Rubber Tire Vehicles	Pickup Truck	1FTBF2B60FEC64755	1/1/2015	Poor	1	35,253	SRTA	2015	Yes	FRD - Ford Motor Corporation	F250	By Policy	Bus	1	30916	26-27	18-19	In Service	Mileage	7/10/2026
121	54524	Automobiles	Sports Utility Vehicle	1FM5K8F83EGC38320	8/11/2014	Poor	1	41,923	SRTA	2014	Yes	FRD - Ford Motor Corporation	Explorer	By Policy	Unknown	1	36365	26-27	18-19	In Service	Mileage	7/10/2026
120	58169	Automobiles	Sports Utility Vehicle	1FMJU2A53EEF47798	6/21/2014	Poor	1	47,878	SRTA	2014	Yes	FRD - Ford Motor Corporation	Expedition	Underway	Commuter Bus	1	42450	26-27	17-18	In Service	Mileage	7/10/2026
822	154453	Trucks and other Rubber Tire Vehicles	Pickup Truck	1FTBF2B61FEA83390	1/1/2014	Poor	1	33,481	SRTA	2015	Yes	FRD - Ford Motor Corporation	F250	Underway	Demand Response	1	29685	26-27	17-18	In Service	Mileage	7/10/2026
821	119824	Automobiles	Sports Utility Vehicle	1FMCU9J95EUD95470	1/1/2014	Poor	1	31,955	SRTA	2014	Yes	FRD - Ford Motor Corporation	Escape	Underway	Bus	1	28332	26-27	17-18	In Service	Mileage	7/10/2026
819	62998	Automobiles	Other Support Vehicle	2C4RDGBG9ER361870	1/1/2014	Poor	1	21,721	SRTA	2014	Yes	DTD - Dodge Division - Chrysler Corporation	Grand Caravan	Underway	Bus	1	19258	26-27	23-24	In Service	Mileage	7/30/2026
818	77533	Automobiles	Other Support Vehicle	2C4RDGBG0ER345167	1/1/2014	Poor	1	21,721	SRTA	2014	Yes	DTD - Dodge Division - Chrysler Corporation	Grand Caravan	Underway	Bus	1	19258	26-27	23-24	In Service	Mileage	7/30/2026
815	157853	Automobiles	Sedan/Station Wagon	3FAHP0CG5AR404345	1/1/2010	Poor	1	23,442	SRTA	2010	Yes	FRD - Ford Motor Corporation	Fusion	Underway	Demand Response	1	21013	26-27	19-20	In Service	Mileage	7/10/2026
814	115083	Automobiles	Sports Utility Vehicle	1FMCU9EG2AKC84602	1/1/2010	Poor	1	26,270	SRTA	2010	Yes	FRD - Ford Motor Corporation	Escape	Underway	Bus	1	22294	26-27	13-14	In Service	Mileage	7/10/2026
119	25174	Trucks and other Rubber Tire Vehicles	Other Support Vehicle	1GBJK74689E149671	9/12/2009	Poor	1	33,954	SRTA	2009	Yes	CMD - Chevrolet Motor Division - GMC	Silverado	By Policy	Commuter Bus	1	28192	26-27	13-14	In Service	Mileage	7/10/2026
817	116287	Trucks and other Rubber Tire Vehicles	Pickup Truck	1GC0KVCG9BF177517	1/1/2008	Poor	1	104,413	SRTA	2010	Yes	GMC - General Motors Corporation	1500	Underway	Bus	1	30000	26-27	11-12	In Service	Mileage	7/10/2026
816	116287	Trucks and other Rubber Tire Vehicles	Pickup Truck	1GDJK34618E151695	1/1/2008	Poor	1	84,279	SRTA	2008	Yes	GMC - General Motors Corporation	2500	Underway	Bus	1	69976	26-27	11-12	In Service	Mileage	7/10/2026
811	103197	Automobiles	Sedan/Station Wagon	1FAFP36364W150132	1/1/2000	Poor	1	28,920	SRTA	2004	Yes	FRD - Ford Motor Corporation	Focus SW	Underway	Bus	1	22000	26-27	09-10	Out of Service	Mileage	7/10/2026

A.5.3 Equipment

Asset ID	Description	External ID	In Service Date	Cost (Purchase)	Subtype	Year	Manufacturer	Model	Type	Class	Useful Life Age	Service Status	Scheduled Replacement Cost	Scheduled Replacement Year	Policy Replacement Year	Replacement Status	Location	TERM Rating	TERM Condition	Organization	Last Life Cycle Action	Life Cycle Action Date
COMMU12A	CamerasGPSSecurity System		4/18/2011	\$965,249	Other Communications Equipment	2011	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	120	Out of Service	1112767	26-27	20-21	Underway	null	Poor	1	SRTA	Condition	7/10/2026
AVL SYSTEM	AUTOVEHICLE LOCATION		3/13/2014	\$754,122	Other Communications Equipment	2014	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	120	In Service	841304	26-27	23-24	Underway	null	Poor	1	SRTA	Condition	7/10/2026
COMMUNICAT	Routers/DVRs on Buses APCs		12/31/2014	\$582,424	Other Communications Equipment	2014	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	120	In Service	649757	26-27	24-25	Underway	null	Poor	1	SRTA	Condition	7/10/2026
505	Fare Collections System (Fareboxes & Vault)		4/1/2003	\$495,938	Fare Collection Systems	2003	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	144	In Service	597306	26-27	14-15	Underway	YRK-ADM	Poor	1	SRTA	Condition	7/10/2026
RAD-01	York Adams and Northumberland Radio System (Mobile & Base Stations)		11/2/2016	\$424,863	Radios	2015	(no data recorded)	XPR 5350s XPR 5550 and XPR 7550s	Communications Equipment	Capital Equipment	120	In Service	479194	26-27	26-27	By Policy	null	Poor	1.5	SRTA	Condition	7/10/2026
APC SYSTEM	APC Units (FR) APC-210 24v System		6/1/2015	\$372,697	Other Communications Equipment	2016	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	120	In Service	415784	26-27	24-25	Underway	null	Poor	1	SRTA	Condition	7/10/2026
ITS	Upgrade communication system (hard drives routers ITS)		6/30/2016	\$235,701	Other Communications Equipment	2016	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	120	In Service	265842	26-27	25-26	By Policy	null	Poor	1	SRTA	Condition	7/10/2026
CE2302	EFX-60 In-Ground 4 Post lift		3/7/2013	\$181,169	Bus Maintenance Equipment	2013	(no data recorded)	(no data recorded)	Maintenance Equipment	Capital Equipment	120	In Service	204337	26-27	22-23	Underway	null	Poor	1	SRTA	Condition	7/10/2026
GATEWAY4	Tkt Machs Stock Server		5/17/2007	\$164,010	Fare Collection Systems	2007	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	144	Out of Service	199706	26-27	18-19	Underway	null	Poor	1	SRTA	Condition	7/10/2026
OE-00001	YORK BOARDROOM TECH UPGRADE		5/21/2025	\$145,464	Other Communications Equipment	2025	NONE	NONE	Communications Equipment	Capital Equipment	120	In Service	162281	34-35	34-35	By Policy	null	Excellent	4.9	SRTA	Condition	7/10/2026
2950-54	Server and IT upgrades with storage		6/30/2016	\$140,961	Hardware	2016	Dell	(no data recorded)	IT Equipment	Capital Equipment	48	Out of Service	155546	26-27	19-20	Underway	null	Poor	1	SRTA	Condition	7/10/2026
RAD-05	USTA/Montour Radio System (Mobile & Base Station)		7/1/2016	\$119,329	Radios	2015	(no data recorded)	XPR 5350s XPR 5550 and XPR 7550s	Communications Equipment	Capital Equipment	120	In Service	134589	26-27	26-27	By Policy	null	Poor	1.5	SRTA	Condition	7/10/2026
CE-ME-DAU-MOBILE LIFTS	Total of 8 Stertil Koni ST-1085 Mobile Lifts.		9/11/2024	\$113,802	Bus Maintenance Equipment	2024	Stertil Koni	ST-1085	Maintenance Equipment	Capital Equipment	120	In Service	126958	34-35	34-35	By Policy	null	Excellent	4.75	SRTA	Condition	7/10/2026
SHOP15	Lifts Body Shop/Bay 6&7		5/20/2003	\$91,993	Bus Maintenance Equipment	2003	(no data recorded)	(no data recorded)	Maintenance Equipment	Capital Equipment	120	Out of Service	110796	26-27	12-13	Underway	null	Poor	1	SRTA	Condition	7/10/2026
RAD-02	Cumberland Radio System (Mobile & Base Station)		11/2/2016	\$89,112	Radios	2015	(no data recorded)	XPR 5350s XPR 5550 and XPR 7550s	Communications Equipment	Capital Equipment	120	In Service	100508	26-27	26-27	By Policy	null	Poor	1.5	SRTA	Condition	7/10/2026
SHOP84	Bin System For Parts Inventory		11/21/2011	\$86,453	Bus Maintenance Equipment	2011	(no data recorded)	(no data recorded)	Maintenance Equipment	Capital Equipment	120	In Service	98581	26-27	21-22	Underway	null	Poor	1	SRTA	Condition	7/10/2026
BUSES #110	Cameras And GPS System		3/31/2011	\$86,053	Other Communications Equipment	2011	(no data recorded)	(no data recorded)	Communications Equipment	Capital Equipment	120	Out of Service	99204	26-27	20-21	Underway	null	Poor	1	SRTA	Condition	7/10/2026
RAD-06	Perry Radio System (Mobile & Base Station)		12/1/2016	\$75,299	Radios	2016	(no data recorded)	XPR 5350s XPR 5550 and XPR 7550s	Communications Equipment	Capital Equipment	120	In Service	84004	26-27	26-27	By Policy	null	Poor	1.5	SRTA	Condition	7/10/2026

							XPR 5350s XPR 5550 and XPR 7550s													
RAD-04	Franklin Radio System (Mobile & Base Station)	3/4/2016	\$62,110	Radios	2015	(no data recorded)	Communications Equipment	Capital Equipment	120	In Service	70053	26-27	25-26	By Policy	null	Poor	1.5	SRTA	Condition	7/10/2026
SHOP14	Lift 1&2 And Related Work	2/1/2003	\$58,550	Bus Maintenance Equipment	2003	(no data recorded)	Maintenance Equipment	Capital Equipment	120	Out of Service	70517	26-27	12-13	Underway	null	Poor	1	SRTA	Condition	7/10/2026

A.6 Facilities Inventory and Condition Assessment (last updated FY2026)

A.6.1 Facilities Inventory

Administrative Facilities										
Asset ID	Organization	Cost (Purchase)	TERM Condition	Facility Name	Type	Subtype	Service Status	Scheduled Replacement Year	Last Life Cycle Action	Life Cycle Action Date
HBG-ADM	SRTA	\$300,000	2.34	Harrisburg Administrative Building	Administrative Office / Sales Office	Other Support Facility	In Service	26-27	Condition	46213
GTY-ADM	SRTA	\$1,200,000	3.82	Gettysburg Administrative Building	Combined Administrative and Maintenance Facility	Administration Building	In Service	26-27	Condition	46213
ELY-ADM	SRTA	\$244,575	3.6	Elysburg Administrative Building	Combined Administrative and Maintenance Facility	Administration Building	In Service	26-27	Condition	46213
YRK-ADM	SRTA	\$6,570,644	3.8	York Administrative Building	Combined Administrative and Maintenance Facility	Administration Building	In Service	27-28	Condition	46213

Passenger Facilities										
Asset ID	Organization	Cost (Purchase)	TERM Condition	Facility Name	Type	Subtype	Service Status	Scheduled Replacement Year	Last Life Cycle Action	Life Cycle Action Date
YRK-TC	SRTA	\$2,116,023	3.85	York -Transfer Center	Bus Transfer Station	Bus Station	In Service	31-32	Condition	46213
GTY-TC	SRTA	\$1,757,399	3.98	Gettysburg-Transit Center	Bus Transfer Station	Bus Station	In Service	42-43	Condition	46213

Parking Facilities										
Asset ID	Organization	Cost (Purchase)	Term Condition	Facility Name	Type	Subtype	Service Status	Scheduled Replacement Year	Last Life Cycle Action	Life Cycle Action Date
EMG-PRK	SRTA	\$1,890,760	3.75	Emigsville Park & Ride Lot	Surface Parking Lot	Park and Ride Lot	In Service	36-37	Condition	46213
SHW-PRK	SRTA	\$992,865	3.88	Shrewsbury Park and Ride Lot	Surface Parking Lot	Park and Ride Lot	In Service	46-47	Condition	46214

A.6.2 Facilities Condition Assessments

Revenue and Non-Revenue Vehicle Condition Inspection Assessment				CAT-2026	Elysburg-2026	Emigsville PnR-2026	Gettysburg Office-2026	Gettysburg Transfer-2026	King Street Station-2026	Lemoyne-2026	rabbittransit-2026	Shrewsbury PnR-2026	Average
			Rating	2.45	3.60	8.40	3.82	3.98	3.85	4.33	3.80	8.60	4.28
ID	Main Component	Sub-Component	Total	184	234	42	271	219	181	13	323	43	183.38
A.	Substructure			11	16	0	16	16	16	0	16	0	11.4
A.1.		Frame: Support Walls		3	4	N/A	4	4	4	N/A	4	N/A	3.8
A.2.		Frame: Exterior Foundation		3	4	N/A	4	4	4	N/A	4	N/A	3.8
A.3.		Concrete Slab		2	4	N/A	4	4	4	N/A	4	N/A	3.7
A.4.		Frame: Beams, Trusses, & Columns		3	4	N/A	4	4	4	N/A	4	N/A	3.8
B.	Roof			9	12	0	12	12	10	0	16	0	8.9
B.1.		Drains, Gutters, & Downspouts		2	4	N/A	4	4	2	N/A	4	N/A	3.3
B.2.		Support Structures		3	4	N/A	4	4	4	N/A	4	N/A	3.8
B.3.		Surface: Shingles/Membrane		1	4	N/A	4	4	4	N/A	4	N/A	3.5
B.4.		Mechanical		3	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	3.5
C.	Exterior Shell			18	24	0	24	20	20	0	23	0	16.1
C.1.		Exterior Windows		4	4	N/A	4	4	4	N/A	4	N/A	4.0
C.2.		Exterior Doors		3	4	N/A	4	4	4	N/A	4	N/A	3.8
C.3.		Structure: Siding Material		3	4	N/A	4	4	4	N/A	4	N/A	3.8
C.4.		Garage Doors		2	4	N/A	4	N/A	N/A	N/A	3	N/A	3.3
C.5.		Mechanical: Conduit, Gas Meters, Utility Box		3	4	N/A	4	4	4	N/A	4	N/A	3.8
C.6.		Surface (Paint, Coating, Brick, etc.)		3	4	N/A	4	4	4	N/A	4	N/A	3.8
D.	Interior: Offices, Break Room, Board Room, Mechanical			27	35	0	27	20	27	0	32	0	21.0
D.1.		Floor Tile		2	4	N/A	4	N/A	4	N/A	3	N/A	3.4
D.2.		Carpet		3	3	N/A	N/A	N/A	N/A	N/A	3	N/A	3.0
D.3.		Doors		3	4	N/A	4	4	4	N/A	3	N/A	3.7
D.4.		Structure: Walls, Foundation, Trusses		4	4	N/A	4	4	4	N/A	4	N/A	4.0
D.5.		Surface: Paint		3	4	N/A	3	4	3	N/A	3	N/A	3.3
D.6.		Insulation		3	4	N/A	4	4	4	N/A	4	N/A	3.8
D.7.		Mechanical: Junction Box, Utility, Vents		3	4	N/A	4	4	4	N/A	4	N/A	3.8
D.8.		Stairs: Surface/Structure		3	4	N/A	N/A	N/A	N/A	N/A	4	N/A	3.7
D.9.		Ceiling Tiles		3	4	N/A	4	N/A	4	N/A	4	N/A	3.8
E.	Interior: Maintenance Shop & Parts Storeroom			11	19	0	19	0	0	0	22	0	8.9
E.1.		Structure: Walls, Frame, Trusses		2	3	N/A	4	N/A	N/A	N/A	4	N/A	3.3
E.2.		Surface: Paint, Walls		1	4	N/A	3	N/A	N/A	N/A	3	N/A	2.8
E.3.		Stairs: Surface/Structure		N/A	3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	3.0
E.4.		Flooring: Epoxy Coating, Uneven, Condition		1	3	N/A	N/A	N/A	N/A	N/A	3	N/A	2.3
E.5.		Ventilation System		2	N/A	N/A	4	N/A	N/A	N/A	4	N/A	3.3
E.6.		Plumbing: Leaks, Drains		3	2	N/A	4	N/A	N/A	N/A	4	N/A	3.3
E.7.		Ceiling: Leaks; Cracks		2	4	N/A	4	N/A	N/A	N/A	4	N/A	3.5
F.	Plumbing			16	24	0	20	24	16	0	28	0	16.0
F.1.		Boiler/Furnace		3	4	N/A	N/A	N/A	N/A	N/A	4	N/A	3.7
F.2.		Backflow Prevention Device		1	4	N/A	4	4	N/A	N/A	4	N/A	3.4
F.3.		Water Heater		3	4	N/A	4	4	4	N/A	4	N/A	3.8
F.4.		Exposed Pipes (Leaks) and Valves		3	4	N/A	4	4	4	N/A	4	N/A	3.8
F.5.		Fixture: Water Closet		1	4	N/A	4	4	4	N/A	4	N/A	3.5
F.6.		Fixture: Sink/Shower Faucet (leaks)		2	4	N/A	N/A	4	4	N/A	4	N/A	3.6
F.7.		Fixture: Urinal		3	N/A	N/A	4	4	N/A	N/A	4	N/A	3.8

G.	HVAC		13	18	0	20	16	16	0	24	0	13.4
G.1.		Chillers	1	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	2.5
G.2.		Garage Ventilation Fan	2	4	N/A	4	N/A	N/A	N/A	4	N/A	3.5
G.3.		Filters	2	3	N/A	4	4	4	N/A	4	N/A	3.5
G.4.		Individual AC Units	2	3	N/A	4	4	4	N/A	4	N/A	3.5
G.5.		Interior Venting/Diffuser, Vent Flu Pipes	3	4	N/A	4	4	4	N/A	4	N/A	3.8
G.6.		Disconnects	3	4	N/A	4	4	4	N/A	4	N/A	3.8
H.	Fire Protection System		17	12	0	40	40	4	0	52	0	20.6
H.1.		Control Panel	N/A	N/A	N/A	N/A	4	N/A	N/A	4	N/A	4.0
H.2.		Smoke Detection Devices	N/A	N/A	N/A	4	4	N/A	N/A	4	N/A	4.0
H.3.		Heat Sensing Detectors	N/A	N/A	N/A	4	4	N/A	N/A	4	N/A	4.0
H.4.		Strobe Alarm Lights	N/A	N/A	N/A	4	4	N/A	N/A	4	N/A	4.0
H.5.		Audible Alarm	2	N/A	N/A	4	4	N/A	N/A	4	N/A	3.5
H.6.		Phone Communication Module	N/A	N/A	N/A	4	4	N/A	N/A	4	N/A	4.0
H.7.		Sprinkler System	2	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	3.0
H.8.		Fire Alarm Pull Stations	N/A	N/A	N/A	4	4	N/A	N/A	4	N/A	4.0
H.9.		Fire Extinguisher Cabinets	4	4	N/A	4	4	N/A	N/A	4	N/A	4.0
H.10.		Power Supply Systems	N/A	N/A	N/A	4	N/A	N/A	N/A	4	N/A	4.0
H.11.		Emergency Exit Signs	3	4	N/A	4	4	4	N/A	4	N/A	3.8
H.12.		Stand Pipes/Plumbing	3	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	3.5
H.13.		Emergency Interior Lights	3	4	N/A	4	4	N/A	N/A	4	N/A	3.8
I.	Electrical		24	40	8	40	36	28	2	40	4	27.3
I.1.		Breaker Panel Box	2	4	N/A	4	4	4	N/A	4	N/A	3.7
I.2.		Emergency Pull Box (Shut Off)	3	4	N/A	4	4	N/A	N/A	4	N/A	3.8
I.3.		Junction Box	2	4	N/A	4	4	4	N/A	4	N/A	3.7
I.4.		Light Switches	3	4	N/A	4	4	4	N/A	4	N/A	3.8
I.5.		Electrical Outlets	3	4	4	4	4	4	N/A	4	N/A	3.9
I.6.		Garage Door Controls	2	4	N/A	4	N/A	N/A	N/A	4	N/A	3.5
I.7.		Connections	3	4	N/A	4	4	4	N/A	4	N/A	3.8
I.8.		Light Fixtures (exterior)	3	4	4	4	4	4	1	4	4	3.5
I.9.		Light Fixtures (interior)	3	4	N/A	4	4	4	N/A	4	N/A	3.8
I.10.		Transformer	N/A	4	N/A	4	4	N/A	1	4	0	3.4
J.	Equipment		19	11	4	16	0	4	0	32	4	10.8
J.1.		Paint Booth	2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	2.0
J.2.		Bus Wash Rack System	1	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	2.5
J.3.		Cyclone Vehicle Cleaning System	1	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	2.5
J.4.		8 Station Lube System	N/A	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	4.0
J.5.		Rotary Lift	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	#DIV/0!
J.6.		Air Compressor	3	3	N/A	4	N/A	N/A	N/A	4	N/A	3.5
J.7.		HQ GFI Bus Fare Collection Safe	3	N/A	N/A	N/A	N/A	N/A	N/A	4	N/A	3.5
J.8.		Backup Generator	2	4	N/A	4	N/A	N/A	N/A	4	N/A	3.5
J.9.		HQ Security CCTV System	3	N/A	4	4	N/A	4	N/A	4	4	3.8
J.10.		Radio System (antenna, base, portables)	4	4	N/A	4	N/A	N/A	N/A	4	N/A	4.0
K.	Site Grounds		19	23	30	37	35	40	11	38	35	29.1
K.1.		Fencing & Gates (condition)	2	N/A	4	4	4	4	1	3	4	3.1
K.2.		Roadways (condition)	2	1	3	4	4	4	2	4	4	3.0
K.3.		Signage (condition)	1	4	4	3	4	4	1	4	4	3.1
K.4.		Pavement Markings (parking lines)	2	3	3	3	3	4	N/A	4	3	3.1
K.5.		Structural/Surface (pavement condition)	2	N/A	4	4	4	4	2	4	4	3.4
K.6.		Sidewalk	N/A	4	N/A	4	4	4	1	4	4	3.5

K.7.		Access Control Devices (function/condition)		2	N/A	N/A	4	N/A	4	N/A	3	N/A	3.3
K.8.		Landscaping		2	4	4	3	4	4	2	4	4	3.4
K.9.		Mechanical (Utilities, Light Posts)		3	4	4	4	4	4	1	4	4	3.5
K.10.		Exterior Lighting		3	3	4	4	4	4	1	4	4	3.4